57 MHZ Meeting Notes 9-16-04

Subject: Status Date: 9/16/04

Attendees: Peter Sushil Frank Al Brian

Action Items:

- Drawing Status
 - Tuning Loop
 - Size vacuum break for system
 - Size ceramic for system for power disipation needed
 - Very small covar next to copper
 - Can the opening be larger
 - 1/2 in larger opening is O.K.
- Ceramic break the same or larger
- Distance to ceramic and body important
- Isolation shielding on edges very important
 - have cooper isolator shield cuff
- braze between covar and copper
- Size is set for loop, braze with no change out required
- Titanium coating may be required on ceramic YES COAT IT Titaniumnitrite preferred 40 angstromes
- Manufacturing
 - Vanes expected delivery today 9/16/04
 - brazing should start ASAP
 - Braze then fix twist
 - One set of deep hole drills is out of spec not considered a show stopper
 - Lifting fixture is assembled
 - END CAPS are moved to central shops
 - Vacuum plugs to be machined
 - •
- Budget
 - Money is lost on Sept 30
 - All bills must be payed by then
 - .
 - •
 - •
 - .
 - •
 - •